

NOTICE TO MARINERS

Please be advised that Moray Offshore Windfarm (West) Limited (Moray West) contracted Geoquip Marine to undertake a geotechnical survey in the Moray West Offshore Wind Farm. Unfortunately, during this survey on the vessel 'Geoquip Saentis' there has been a dropped object incident.

On Thursday 19th December 2019 during CPT survey operations in the Moray West Offshore Wind Farm there were difficulties during recovery of CPT equipment which resulted in the loss of a CPT cone & section of rod at the following approximate location coordinate:

Lat (DDM)	Lon (DDM)
58° 3.100' N	3° 6.763' W

Operations to recover the dropped object are not planned due to the uncertainty of its exact location. The object is considered lost and there is low risk to other users of the sea because the object is inert and located in/below the seabed.




Figure 1: Location of the dropped object.

Dropped Object Parameters

The dropped object is a CPT cone & section of rod (Figure 2) which is a component used during the CPT sampling. The dropped object has the following dimensions:

- 52 cm long (Seismic Cone 23 cm + part of the Seismic Lance 29 cm)




Figure 2: Image of the dropped object.

Fisheries Liaison Officer (FLO) contact details:

Hamish McPherson
Fisheries Liaison Officer
Tel: + 44 (0) 7770 284947
Email: hamishmm@btinternet.com

Developer contact details:

Technical and Survey Planning: Alex Eakin, alex.eakin@edpr.com, 07741 904826
Commercial Fisheries: David O'Sullivan, david.osullivan@edpr.com, 07741 162783
Health, Safety and Other Matters: Tony Blackshaw, Tony.Blackshaw@moraywest.com, 07443 638253