
NOTICE TO MARINERS (NTM)

Issue Date	12 th May 2020
Version	02
Activity Type	Floating LiDAR Buoy Recovered and Ashore

Please be advised that Moray Offshore Windfarm (West) Limited (Moray West) had positioned a Floating LiDAR Buoy and mooring system (clump weight and mooring chain) at the Moray West Offshore Wind Farm Site.

The Floating LiDAR Buoy was safely recovered without incident yesterday 11th May 2020 and is now onshore for maintenance. The Floating LiDAR Buoy will be reinstalled at a later date and a notice to mariners will be issued in advance of this operation.

Floating LiDAR Buoy Original Site Location Coordinates		
Latitude (WGS84 Degrees Decimal Minutes)	Longitude (WGS84 Degrees Decimal Minutes)	
58° 5.381 N	3° 0.877 W	



Floating LiDAR Buoy Original Site Location

Developer contact details:

Technical – Guillermo Tornero, **E**: <u>Guillermo.Tornero@edpr.com</u> **T**: +44 (0) 7741 625376 **QHSSE** – Tony Blackshaw, **E**: <u>Tony.Blackshaw@moraywest.com</u>+, **T**: +44 (0) 7443 638253 **Commercial Fisheries** – David O'Sullivan, **E**: <u>david.osullivan@edpr.com</u>, **T**: +44 (0) 7741 162783